


# IS Cube



**Innovation Solution** 

## Feature

- Bright LCD display for displaying Dimension Data
- High quality Weighing Indicator
- Ultrasound sensor system
- Input prices
- Print the result directty
- Output to PC and ticket printer
- Measure dimension and weigh materail at the same time
- Completely eliminate manual measurement

## Specifications

#### Scale

Available capacities	30kg ~ 1000kg
Resolutions	3000 ~ 6000d
Weight sensor	Loadcell

#### Measurement

Available ranges	30cm ~ 150cm
Increment	0.3 cm
Tolerance	+/- 2cm
Minimum object size	4 x 4 x 4cm
Measurement sensor	Ultrasound

#### Other

Data output	RS-232
Power source	220VAC
Operating temperature	0° ~ 40° C



MK-E1005 Indicator



IS-Cube Indicator

## Dimensions

